

(Autonomous)






Figure 1. Welding Apron



(Autonomous)






Figure 2. Overcoat with shoes



(Autonomous)





Figure 3. Welding Safety glasses



(Autonomous)





Figure 4. Welding helemt



### (Autonomous)






Figure 5. Safety line - Engineering practices lab



(Autonomous)






Figure 6. Safety line - Thermodynamics lab



(Autonomous)







Figure 7. Fire Extinguisher - Aircraft structures lab



### (Autonomous)





Figure~8.~Safety~line~-~Aircraft~structures~lab



(Autonomous)






Figure 9. Safety line - Aircraft systems lab



(Autonomous)







Figure 10. Fire Extinguisher - Aero Engine & Air frame lab



### (Autonomous)





Figure~11.~Safety~line~-~Aero~Engine~&~Air~frame~lab



#### (Autonomous)






Figure 12. Fire Extinguisher - Propulsion lab



### (Autonomous)






Figure 13. Safety line - Propulsion lab



#### (Autonomous)






Figure 14. Safety line - Aerodynamics lab



(Autonomous)






Figure 15. First Aid Box - Workshop Entrance